



Property Completion Agreement

This agreement documents the completion of remedial activities performed on my property. My signature will designate that I am satisfied with the restoration of my property, and that no items are in questions, now, or at any time in the future, except those items listed below, if any.

Property ID: /86 2	,
Property Address: 2620 Saint Paul St	
Owner: MIGHEL VICCARROLL	
Phone:	
Restoration Items in Question:	
Item:	· .
Item:	
Item:	
Item:	
Item:	·
Item:	
Additional Comments:	
I agree restoration is completed, except as noted I do not agree restoration is completed	
MI SUL VILLANGED 1-0604	Contractor's Signature Date





U.S. Environmental Protection Agency Vasquez Boulevard I/70 Superfund Site Replacement Certificate

Property Owner	Miguel Villarreal
Property Address	3620 Sait Paul St.
Property Identification Number	1802

Material Removed	Quantity	Unit Price	Replacement Value
Flower bed area (square feet)	·	\$ 2.50	\$
Itemized plants		\$7.00	\$
Itemized shrubs/bushes	2	\$12.00	\$24.00
Total			\$24.00

The acceptance of the replacement certificate and the signature below is full acknowledgement by the property owner that this is a fair and reasonable compensation for plant materials removed during remediation activities, but not planted or installed by the government or it's contractors.

The total amount of \$24.00	has be	een received by the owner in the f	form of a	
replacement certificate, #12595	, to	be utilized at Paulino's Gardens	, 6300 N.	
Broadway, Denver, CO 80216.		/ / \		
MI 9 el Villameal D	deit	Plan Jan	01-06	D4
Property Owner's Signature	Date	Contractor's Signature	Date	

CHANGE ORDER VBI-70

Property #	
Property Address: <u>366</u>	20 ST Paul
Owner: MIGUEL 1	VILLARREAL
Date: 11-18-03	
Removed FROM	y owner Warts Sick Wall FRONT CORNER TO Jance and well By PRI Contracture
Not be keplace.	. By PRI contractuals
BACK YARD WAR	Nts SOD See ATTALL Sketch.
	50D 12XZZ
	18123> SOD 4 4145, F+ 364 sol FL 3
	0 414 214 304 304 30
	HOUSE
	Remara Side walk
Owner Signature: XMI	19vel VIlla91x02/
d	
Contractor Signature:	tila Sam 11-10-83

676





Consent For Access To Property

RIGHT OF ENTRY TO PREMISES

Grantor (the property owner) consents to and authorizes the United States Environmental Protection Agency (EPA) or its authorized representatives, collectively the Grantee, to enter and perform certain environmental response activities upon the following described premises:

Owner's Name: Miggle	VillArregi	Daytime Phone: 720 - 34/-13/4
	1	, , , , , , , , , , , , , , , , , , ,
	Address: 3620	Daint Paul St
Address of December	Address:	
Addresses of Properties covered by this	Address:	
Agreement:	Address:	
	Address:	

Purpose of Response Activities

The EPA is requesting access to collect soil samples and remove soil that contains elevated concentrations of arsenic and/or lead and may pose a health hazard. The soil will be removed and the excavated area(s) will be replaced with clean materials and restored. This work is being performed under the Vasquez Boulevard/I-70 Superfund Site remediation program.

An EPA representative will contact the Grantor in-person to discuss the work to be performed, the Grantor will have an opportunity to review and approve the planned soil removal, and restoration work before it begins. Once the work is finished, the Grantor will be asked to review the work and confirm that it is complete and meets with the Grantor's approval. Upon completion, the Grantor will receive written documentation from EPA that the property has been remediated.

ENVIRONMENTAL RESPONSE ACTIONS

By signing this Access Agreement, the Grantor is granting the EPA, its employees, contractors and subcontractors the right to enter the property, at all reasonable times and with prior notice, for the sole purpose of performing the work. This access shall remain in effect until the work has been satisfactorily completed. The Grantor also agrees to:





Remover obstruciónes que incluye botes, remolque, vehículos, jugetes de niños, montones de madera, casas de perros, etc.

- Remover de bulbos de flores, o otras plantas que el Otorgante o inquilino del Otorgante quisiera guardar;
- Regar y mantener reemplazo de vegetación, incluso la aplicación de fertilizante, como es necesario subsecuente de la riega inicial por el EPA, a menos que regando está restringido por la Junta de Agua de Denver.
- Permanecer por la guia de Salud y Seguridad proveido por el EPA;
- Si la propiedad está rentado, asiste el EPA a obtener la aprobación del inquilino para acceso a la propiedad a llevar a cabo el trabajo, si el EPA está inhábil a obtener acceso; y
- Permitir a hacer un video y/o tomar fotos de la propiedad incluyendo los areas exterior y interior de edificios.

ACUERDO A NO INTERFERIR


El Otorgante está de acuerdo a no interferir o meterse en cualquier actividades o trabajo hecho, o el equipo usado a llevar de cabo los actividades, o hacer cualquier acciones en respecto de la usa de dicho propiedad que podría arriesgar la salud o bienestar de los Cesionarios o el medio ambiente, o permitir otras personas a usar la propiedad en alguna manera.

Si tiene preguntas sobre este programa, por favor contacta Jennifer Chergo, EPA, (303) 312-6601.

☐ Si yo permito acceso a mi	propiedad	☐ No permito acc	ceso a mi propiedad.
Laniguel Villamea	9-12-03	- Ilan	Sarah 9720
Firma	Fecha	Firma	Fecha
☐ Me gustaría ser present	o durante de cualqu	uier colleción de mue	estras.

Property Access Checklist

Property ID: 180 Z	Z		CSTARTED ON://
Property Address: 3620 54.	941	WORK	COMPELTED ON://
Owner: Miguel Villar Address: 3620 St. Pau	real	Renter:	
Address:	. ,	Phone:	
3620 St. Fah	1 5+.	Fax:	
		Cell/Pager:	
Phone: 720 341-13	: 17	Additional	Information:
Fax:	,		
Cell/Pager:	- 10, 0, 0, 0		
	T	./ - >	
Notification Letter	 	115103	By: m. smith
Access Agreement		1/12/03	By: Migh 81 Villarea
Restoration Agreement	Signed: <u>9</u>	115103	By: mignel villarrea
☐ Topsoil Sampling (if applicable)	/_	_/	By:
☐ Disposal Sampling (if applicable)		_/	By:
Garden Sampling (if applicable)	/_	_/	By:
Utility Clearance	Called:	_//	By:
Video/Photos (Before)	On: <u>4</u> /	15/03	By: T. myers
☐ Video/Photos (During)	On:/	/	By:
☐ Video/Photos (After)	On:/	/	By:
☐ Video/Photos (30-Day)	On:/	/	By:
☐ Property Completion Agreement	Signed:	_//	By:
Final Report	Issued:	//_	By:
Air Marianing (or applicable)			
Air Monitoring (as applicable) Community Crew On:	11	By:	
Results:	· <u>·</u>	1 23.	
	<u> </u>	By:	
Results:			
Community Crew On:	//_	Ву:	
Results:		· ·	



Restoration Agreement

The purpose of this agreement is to provide a mutual agreement as to conditions of property prior to remediation activities. This will also serve as decontamination for the purpose of assuring that restoration activities are completed to the satisfaction of the property owner and the United States Environmental Protection Agency (EPA).

Property ID: 1802
Property Address: 3620 St. Paul Strept
Owner: Miguel Villa/(Ca)
Phone: 726 341-1314

On the attached diagram(s) indicate area(s) to excavated and depth of excavation, location of all known utilities, subsurface features, surface structures and landscaping features, access location(s) to be used by contractor, and the direction of North. Indicate distances, depths, material types, etc. Indicate digital photos by referencing the photo-log number with an arrow indicating direction of view.

Items To Be Removed By Owner Before Start Of Remediation: (Use additional sheets as necessary)

The removal, storage, disposal, and/or return of these items is the Owner's responsibility.

Item:	.)
	Tuo cars in back yard
Item:	, , , , , , , , , , , , , , , , , , ,
	misc. Stuff in yard
ltem:	,
	Tires and Stuff by garage
Item:	, , , , , , , , , , , , , , , , , , , ,
	Recycling by patio
Item:	
Item:	
Item:	
Item:	
	Page 1 of
	1 ugv 1 v1



Landscape Inventory (Use additional sheets as necessary)

Item	Quantity	Unit	Condition/Type/Species
Pre-existing property area that is covered with grass.	^6653	Square feet	
Number of trees > 2 inch trunk diameter	10	Each	SEE SKETCH
Number of trees <= 2 inch trunk diameter	8	Each	NA
Number of Sprinkler Zones, Control Valves, Timers, Heads, etc. Attach a sketch of the sprinkler layout.	NA	Each	NJA
Number of and size of each garden/ flower bed area. Attach a sketch of relative sizes and locations.	NA	Each Square Feet	NIA



Project Resources Inc.

ltem	Quantity	Unit	Condition/Type/Species
Agreed upon value of plant materials not to be replaced by contractor. Note this value will be used to issue a plant voucher to the property owner.	ZROS	\$	2 Larger - rose Sushes - wants
Agreed upon list of plant materials that will be replaced by contractor. Be very specific and detailed. Include a sketch of were each plant will be placed by the contractor.	NA	Each	NA
Agreed upon area of property to be replaced with grass sod. Include a sketch of the area(s) to be replaced with grass sod.	1596	SF	SEE SKETCH
Area of City or County property to be landscaped per their requirements. Include a sketch of the area (s)	NA	SF	MA
Medium Rock	3836	SF	SEE SKRICH

Oriveway Gravel

1221 SF See SKR+CH



Additional Comments / Instructions:
With sop.
* Entire back yard is rock
driveway area in front also gets medium river rock
as well as front area wotwo
walk and house.
* Leave all shrubs and large
busies in front yard.

pre-existing damage. B	ner does not want PRI to by checking this box PRI in neg foundation cracks or fiss	s not responsible for any	•
agree	☐ I do not agree	☐ 1 agree	☐ I do not agree
MI JUE Owner's Signature	1//27782/ Date 9/15/03	Contractor's Signature	9/13/07 Date

This spreadsheet performs screening level calculations to estimate the effect of peeling leaded paint on the average concentration of lead in yard soil 3620 St. Paul St.

INPUTS	Variable	Units	House
General	Mixing depth in yard	cm	2.54
	Mixing depth in yard	inches	1
	Soil density	g/cm3	2.5
	RBC in soil	mg/kg	400
	Bkg in clean fill	mg/kg	50
	•		Small
House-specific	Area of the exposure unit	m2	78.03855
•	Area of the exposure unit	ft2	840
	Concentration of lead in paint	mg/cm2	13
	Area of peeling paint	m2	9.522576
	Area of peeling paint	ft2	24.12
COMPUTATIONS	•		
	Mass of lead from paint	mg	1.2E+06
	Volume of soil	cm3	2.0E+06
	Mass of soil	kg	5.0E+03
	Incremental concentration	mg/kg	249.8
	Maximum acceptable area of p		13.3
	Maximum acceptable area of p	• • • •	143.6
DECISION			ок

Address:	3620 St. Paul St.		······································		Date:	38574.00		
Owner:	Miguel and Juan	Villar	real		Telephone #:	(720) 34	1-1314	
lot Plan:								· · · · · · · · · · · · · · · · · · ·
							٠ ا	
						Ds.	Prody To	>
						2 10	1802	
							1800	
			see attached					
٠								
						·		
		Exterior Wa				Doors/		
	Material	deteriorated		VDE (Load)	Matarial	deteriorated		VDE (Load)
North	Material			XRF (Lead)	Material			XRF (Lead)
South	Material	deteriorated		XRF (Lead)	Material	deteriorated		XRF (Lead)
South East	Material	deteriorated		XRF (Lead)	Material	deteriorated		XRF (Lead)
South	Material	deteriorated		XRF (Lead)	Material Total	deteriorated		XRF (Lead)
South East	Total	deteriorated Area	Peel/Chip	XRF (Lead)		deteriorated Area	Peel/Chip	XRF (Lead)
South East	Total	0.00 ndow Trim/Fast deteriorated	Peel/Chip		Total	0.00 Patios/Decks	Peel/Chip	
South East West	Total Wir	0.00 ndow Trim/Fast deteriorated Area	Peel/Chip	XRF (Lead)		deteriorated Area 0.00 Patios/Decks	Peel/Chip	XRF (Lead)
South East West North South	Total	0.00 ndow Trim/Fast deteriorated	Peel/Chip		Total	0.00 Patios/Decks deteriorated Area	Peel/Chip s/Porches Peel/Chip	XRF (Lead)
South East West North South East	Total Wir Material wood wood	0.00 ndow Trim/Fas deteriorated Area 9.44 2.78	Peel/Chip	XRF (Lead) 13+-3.1 13+-3.1	Total	0.00 Patios/Decks	Peel/Chip s/Porches Peel/Chip	
South East West North South	Total Wir Material wood	0.00 ndow Trim/Fas deteriorated Area 9.44 2.78	Peel/Chip	XRF (Lead)	Total Material wood	0.00 Patios/Decks deteriorated Area 7.85	Peel/Chip s/Porches Peel/Chip	XRF (Lead)
South East West North South East	Total Wir Material wood wood Total	0.00 ndow Trim/Fast deteriorated Area 9.44 2.78 4.05	Peel/Chip	XRF (Lead) 13+-3.1 13+-3.1	Total Material wood Total	0.00 Patios/Decks deteriorated Area 7.85	Peel/Chip	XRF (Lead) 3.5+-1.2
South East West North South East	Total Wir Material wood wood Total	0.00 ndow Trim/Fast deteriorated Area 9.44 2.78 4.05 16.27	Peel/Chip	XRF (Lead) 13+-3.1 13+-3.1	Total Material wood Total	0.00 Patios/Decks deteriorated Area 7.85 Structures/G	Peel/Chip	XRF (Lead) 3.5+-1.2
South East West North South East West	Total Wir Material wood wood Total	0.00 ndow Trim/Fast deteriorated Area 9.44 2.78 4.05	Peel/Chip	XRF (Lead) 13+-3.1 13+-3.1	Total Material wood Total Miss	0.00 Patios/Decks deteriorated Area 7.85	Peel/Chip	XRF (Lead) 3.5+-1.2
South East West North South East West	Total Wir Material wood wood Total Metal	0.00 ndow Trim/Fast deteriorated Area 9.44 2.78 4.05 16.27 Trim/Gutters/D deteriorated deteriorated deteriorated deteriorated	Peel/Chip cia/Soffit Peel/Chip	XRF (Lead) 13+-3.1 13+-3.1	Total Material wood Total Miss	0.00 Patios/Decks deteriorated Area 7.85 Structures/G deteriorated	Peel/Chip s/Porches Peel/Chip	XRF (Lead) 3.5+-1.2
South East West North South East West	Total Wir Material wood wood Total Metal	0.00 ndow Trim/Fast deteriorated Area 9.44 2.78 4.05 16.27 Trim/Gutters/D deteriorated deteriorated deteriorated deteriorated	Peel/Chip cia/Soffit Peel/Chip	XRF (Lead) 13+-3.1 13+-3.1	Total Material wood Total Miss	0.00 Patios/Decks deteriorated Area 7.85 Structures/G deteriorated	Peel/Chip s/Porches Peel/Chip	XRF (Lead) 3.5+-1.2
South East West North South East West	Total Wir Material wood wood Total Metal	0.00 ndow Trim/Fast deteriorated Area 9.44 2.78 4.05 16.27 Trim/Gutters/D deteriorated deteriorated deteriorated deteriorated	Peel/Chip cia/Soffit Peel/Chip	XRF (Lead) 13+-3.1 13+-3.1	Total Material wood Total Miss	0.00 Patios/Decks deteriorated Area 7.85 Structures/G deteriorated	Peel/Chip s/Porches Peel/Chip	XRF (Lead) 3.5+-1.2

(24+12)(12+12)-(24×12) No lead Concentration of Delinarified | (36)(24) - 288 864-288: 576 Reported for The garage 3 (25+12)(33+12)-(25×33) (37) 45) - 825 1665 -825 = 840 w 25.2"

3620 St. Paul St.

Address: Date:	3620 St. Pa 8/8/2005	ul 5			Investigator Time Started	CM &WH 2:20pm					
House	Garage	Shed				North	South	East	West ⁻		
Drawing Number		Painted Surface	Material	Color	Total Area of Element	Percent Deteriorated	Deteriorated Area	XRF#	XRF Value	Pos/Neg	Notes
		Back Patio Floor	Concrete	red			10.00	84	0.01+-0.02	Neg.	
3	3	Back Patio Posts (5)	Wood	red	39.27	20%	7.85	85	3.5 +- 1.2	Pos.	
						-		ļ			
								<u> </u>			
	ļ							-	ļ		
	 	·					 				
ļ						<u> </u>		 	1		
·					 			 	 		•
<u> </u>	+				1			 	 		
-	-										
						· · · · · · · · · · · · · · · · · · ·					
		<u> </u>									
					·						
	<u> </u>								ļ		
								<u> </u>			
	<u> </u>										
	ļ						ļ <u>.</u>	<u> </u>	ļ. <u></u>		
	ļ										
			1				ļ		<u> </u>		
		1			İ	1	1		1		1

•


Address: Date:	3620 St. Pa 8/8/200				Investigator Time Started	CM & WH 2:20pm					
House	Garage	Shed				North	South	East	West		
Drawing Number	Photo Number	Painted Surface	Material	Color	Total Area of Element	Percent Deteriorated	Deteriorated Area	XRF#	XRF Value	pos/neg	Notes
2	2	soffit/fascia	wood	white	18.88	50%	9.44	see 92	13+-3.1	Pos.	
	1	porch trim	wood	white			3.00	90	0.00+-0.06		
	 	fence to back yard	wood	white		<u> </u>	3.00	91	0.01+-0.15		
<u> </u>	1								1		
	<u> </u>						<u> </u>		<u> </u>	<u> </u>	
							<u></u>		<u> </u>		
	<u> </u>				<u> </u>					1	
	<u> </u>				<u> </u>					·	
					<u> </u>						<u> </u>
<u> </u>			_		<u> </u>						
L	<u> </u>						<u></u> _				<u> </u>
							ļ <u></u>		<u> </u>	ļ	<u> </u>
								ļ	<u> </u>		
	ļ							ļ ·			
	ļ						<u> </u>				
L			_								
	1										
		<u></u>						ļ			· · · · · · · · · · · · · · · · · · ·
L		<u> </u>	1								
	<u> </u>										
l .	1	1	1 1			1	1	I	1		

Address: Date:	3620 St. Pa 8/8/2005				Investigator Time Started	WH & CM 2:20:00 PM					
House	Garage	Shed				North .	South	East	West		
Drawing Number	Photo Number	Painted Surface	Material	Color	Total Area of Element	Percent Deteriorated	Deteriorated Area	XRF#	XRF Value	pos/neg	Notes
	4	Soffit/ Fascia	Wood	White	27.75	10%	2.78	See 92	Pes /35	, i pos	
	I	Back Patio Wall/Screening	Wood	red	45.50	50%	22.75	See 93	0.42+-0.24	neg	
			<u> </u>	-	·						
	ļ		ļ								
L	<u> </u>		<u> </u>	<u> </u>	<u></u>		<u> </u>	 	<u> </u>	ļ	
	ļ		 								
<u> </u>	-		 	<u> </u>	 	 		 -		<u> </u>	
<u> </u>	 		 			 		 	 	<u> </u>	
	-		 		 	 	 	 	<u> </u>	<u> </u>	
	 	<u> </u>	 		 	-			ļ		
			1		<u> </u>	<u> </u>			 		
								 			
		<u> </u>	j .					† · · · · · · · · · · · · · · · · · · ·			
	<u> </u>					1					
						<u> </u>		ļ			
	ļ		ļ			 					<u> </u>
	ļ			_							
	<u> </u>		ļ					<u> </u>	ļ	· · · · · · · · · · · · · · · · · · ·	
	 		ļ		ļ <u> </u>	 		 	ļ		
		<u> </u>	<u> </u>	<u>-</u>		1			ļ <u>-</u>		
	 	 	 			 		ļ	ļ <u>-</u>		
ł	1	1	1 1			I		1	1	1	1

.

•

Address: 3620 St.Paul Investigator: WH &CM Time started: Date: 8/8/2005 2: 20pm Garage Shed North South East West House Drawing Photo Percent Number **Total Area of Element** Deteriorated Deteriorated Area XRF# XRF Value pos/neg Notes Number **Painted Surface** Material Color Porch ceiling and beams 96.00 30% 28.80 0.05+-0.23 wood white 88 Neg. Porch Floor 3.75 Gray 0.00+-0.01 Neg. Concrete 87 Soffit/ Fascia 13.50 30% Wood White 4.05 92 13+-3.1 Pos.



Real Property Records

Date last updated: Friday, July 11, 2003

O Real Property Search

If you have a question about the value, ownership, or characteristics of this property, or any other property in Denver, please call the Assessor at 720-913-4162.

Link to property tax information for this property
Link to property sales information for this neighborhood
Link to property sales information for all Denver neighborhoods

PROPERTY INFORMATION

Property Type: Residential

Name and Address Information

VILLARREAL, MIGUEL A & JUAN

3620 SAINT PAUL ST

DENVER, CO 80205

Parcel: 0225110009000

Legal Description

L 9 & 10 & S1/2 OF L 8 BLK 8

CHARLOTTE MCKEES ADD

RESIDENTIAL

Property Address:

Tax District

3620 SAINT PAUL ST

DENV

Assessment Information

	Actual	Assessed	Exempt	Taxable
Current Year				
Land "	31000	2470		
Improvements	125200	9970		
Total	156200	12440	0	12440
Prior Year				,
Land	24100	2210		
Improvements	102200	9350		
Total	126300	11560	0	11560

Style: One Story

Year Built: 1946

Building Sqr. Foot: 765

Bedrooms: 2

Baths Full/Half: 1/0

Basement/Finished: 765/660

Lot Size: 7,810


Zoning: R2

Reception No.: JT00097750

Recording Date: 05/30/02

Sale Price: 10

Mill Levy: 59.855



TARGET SHEET EPA REGION VIII

EPA REGION VIII SUPERFUND DOCUMENT MANAGEMENT SYSTEM

DOCUMENT NUMBER: 1051143

	000	OWIENT NOWIDER. 1001110
Si	TE NAME:	VASQUEZ BOULEVARD AND I-70
DO	DOUMENT DATE:	08/08/2005
Di	ue to one of the fol	DOCUMENT NOT SCANNED lowing reasons:
7	PHOTOGRAPHS	·
	3-DIMENSIONAL	
	OVERSIZED	
V	AUDIO/VISUAL	
	PERMANENTLY	BOUND DOCUMENTS
	POOR LEGIBILIT	Y
	OTHER	•
	NOT AVAILABLE	
		MENTS NOT TO BE SCANNED Data Validation, Sampling Data, CBI, Chain of Custody)
DC	CUMENT DESCR	IPTION:
	1 - PROPERTY D	PERTY VIDEO, PROPERTY #1802 ATA CD HOTO CD